

U.S. PTO  
09/133615



Fig. 1




Fig. 2




Fig. 3





FIG. 4

190






Fig. 8




Fig 5




Fig. 6




Fig 7




Fig. 11




Fig. 10




FIG. 12






FIG. 13






FIG. 16




FIG. 17




FIG. 18




FIG. 19





FIG. 20 A

SEALING SECTION



CUTION

170  
Drinks  
Mozan




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG. 29




FIG. 30




FIG. 31




FIG. 32






FIG. 33






FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG 39a




FIG. 41




FIG. 42







FIG. 43




**FIG. 44**







**FIG. 45**




**FIG. 46**




**FIG. 47**







**FIG. 51**




**FIG. 52**




**FIG. 50**



**FIG. 53**



**FIG. 57**



Je542 U.S. PRO

09/133615



08/137/98

**ATTACHMENT C**